

What is **wrong** with this vending machine called **the 3-Select**?



1

Machine too large. Difficult to place in a corner.

This style machine is designed **horizontally**. It requires too much floor space making it difficult to place in a corner of a room.

2

Cheap Locks

The locks are a cheap, **flat-key** style, which are very easy to **pick** or **break** open.

3

Servicing Nightmare!

This 3-Select machine does **not** have interchangeable canisters. Therefore, you will not be able to purchase extra canisters to **refill** them back at your **home** and then swap out the empty canisters for the filled canisters at the stores. Your service time will then be **double** what it would be with our 4-in-1 vending machines.

4

Lead Paint on Cheaply Constructed Case

The candy and nuts touches the **lead** paint on the case of the machine making it very **dangerous** to eat!

The **case** that holds the money and candy is either constructed of **cheap** plastic or **cheap** scrap metal, like aluminum. These are both very easy to **crack**, **dent**, or **break into** the case and **steal** your money!

5

Cheap Coin Mechanism Accepts Slugs and Jams

Coin mechanisms are constructed of **cheap**, scrap metal, like aluminum, only made to work for about one (1) year and then need **replacing!** Most of these 25¢ coin mechanisms **cannot** be swapped out for 50¢ coin mechanisms.

6

Difficult to Remove Money

Removing the money is very difficult on all 3-Select machines. You must **pull** the machine out from the **wall**, and **lift** it around in order to remove the **money**. Why? Because the access door is **behind** the machine, not on the **front** of the machine where it should be!

WARNING: Manufactured in China.

Most of these 3-Select machines are manufactured in China and only have a life **expectancy** of about one (1) year.

Less Profits

The 3-Select will **never** make as **much** money as our 4-in-1 machine, in part, because there is one less selection.