

What is **wrong** with this vending machine called **the 3-Select**?



- 1 Machine too large. Difficult to place in a corner.**
This style machine is designed **horizontally**. It requires too much floor space making it difficult to place in a corner of a room.
- 2 Cheap Locks**
The locks are a cheap, **flat-key** style, which are very easy to **pick** or **break** open.
- 3 Servicing Nightmare!**
This 3-Select machine does **not** have interchangeable canisters. Therefore, you will not be able to purchase extra canisters to **refill** them back at your **home** and then swap out the empty canisters for the filled canisters at the stores. Your service time will then be **double** what it would be with our 4-in-1 vending machines.
- 4 Lead Paint on Cheaply Constructed Case**
The candy and nuts touches the **lead** paint on the case of the machine making it very **dangerous** to eat!
The **case** that holds the money and candy is either constructed of **cheap** plastic or **cheap** scrap metal, like aluminum. These are both very easy to **crack**, **dent**, or **break into** the case and **steal** your money!
- 5 Cheap Coin Mechanism Accepts Slugs and Jams**
Coin mechanisms are constructed of **cheap**, scrap metal, like aluminum, only made to work for about one (1) year and then need **replacing!** Most of these 25¢ coin mechanisms **cannot** be swapped out for 50¢ coin mechanisms.
- 6 Difficult to Remove Money**
Removing the money is very difficult on all 3-Select machines. You must **pull** the machine out from the **wall**, and **lift** it around in order to remove the **money**. Why? Because the access door is **behind** the machine, not on the **front** of the machine where it should be!

WARNING: Manufactured in China.

Most of these 3-Select machines are manufactured in China and only have a life **expectancy** of about one (1) year.

Less Profits

The 3-Select will **never** make as **much money** as our 4-in-1 machine, in part, because there is one less selection.